

FAA-PMA Parts Eligibility for **Continental** Engines

Click here and enter the Continental part number
you are searching for.

Note: If you do not know the part number,
click the button below.

Acrobat



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA1000	19	Continental Engines: C-125-2; C-145-2, 2H; C75-8, 12, 14, 16, 8F, 12F, 14F, 16F, C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA1004	16	Continental Engines: C125-2; C145-2, 2H; C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E
SA1007	26	Continental Engines: C125-2; C145-2, 2H; C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA10200-A1	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA10200-A1 CK		Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA10200-A20P		Continental Engines: O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D
SA10200-A20P CK		Continental Engines: O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D
SA10200-A21	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F
SA10200-A22	97	Continental Engines: C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA10200-A23	97	Continental Engines: GO-300-A, C, D, E, F
SA10202	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA10203	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA10204	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA10205	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA10206	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA10209	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA2000	23	Continental Engines: C-125-2; C145-2, 2H; C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA20202	54	Continental Engines: C125-2; C145-2, 2H; GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-346 IO-360-A, AB, C, CB, D, DB, D15, DB15, G, GB, H, HB, J, JB, K, KB; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; LTSIO-360-E, EB, KB; O-300-A, B, C
SA2025	137	Continental Engines: C125-2; C145-2, 2H; O-200-A, B; O-300-A, B, C, D; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B, C, D; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-52
SA2026	77	Continental Engines: IO-470-C, D, E, F3, F4, F5, F7, G, H, J, K, K14, L, L8, M, N, R, S, V, F18, F19, F23 F26; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B; IO-520-A, D, E, F, J, K, L; TSIO-520-AE, C, G, H, M, P, R; LTSIO-520-AE; IO-550-G
SA2101	23	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA2102	23	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E
SA2103	24	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; C125-2; C-145-2, 2H; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA2105	34	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; C-125-2; C-145-2, 2H; O-200-A, B; O-300-A, B, C, D



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA21051	76	Continental Engines: A65, 75; C125-2; C145-2, 2H; C75, 85, 90; O-200-A, B; O-300-A, B, C, D
SA2106	25	Continental Engines: C125-2; C145-2, 2H; C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA2107	32	Continental Engines: C125-2; C145-2, 2H; C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA21114	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA21153	1	Continental Engines: O-300-A, B, C, D; GO-300-A, C, D, E; C-75, 85, 90; O-200-A, B; A65; A-75; C125-2; C145-2, 2H
SA21185		Continental Engines: A65, 75; C75, 85, 90; O-200-A, B
SA21218	102	Continental Engines: C-75, 85, 90; O-200-A, B
SA21247	102	Continental Engines: TSIO-470-B1, B2, B3, C, D
SA21284	90	Continental Engines: A65, A75; C-125-2; C-145-2, 2H; C75, C85, C90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA21323	76	Continental Engines: C-125-2; C-145-2, 2H; O-300-A, B, C, D; C-75, 85, 90; O-200-A, B; A-65, 75
SA21361	14	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; O-300-A, B, C, D; O-200-A, B
SA21477	78	Continental Engines: A65, A75; C125-2; C145-2, 2H; GO-300-A, C, D, E; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; O-200-A, B; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA22022	78	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-J, K; LTSIO-360-E, EB, KB; O-200-A, B; O-300-A, B, C, D; O-470-A, E, J; TSIO-360-A, B, C, D, DB, E
SA22133	90	Continental Engines: A65, A75; C75, C85, C90; C-125-2
SA22139	78	Continental Engines: A65, A75; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-550-G; LTSIO-360-E, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB; TSIO-520-BE
SA22250	76	Continental Engines: C125-2; C145-2, 2H; C75, 85, 90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA22344	76	Continental Engines: C-75, C85, C90; O-200-A, B
SA22350	76	Continental Engines: C-75, C85, C90; O-200-A, B
SA22354	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F
SA22355	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B
SA22387	90	Continental Engines: A65; A75; C75; C85; C90; O-200-A, B
SA22532	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA22534	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA22535	78	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, C5, C6, C7, CB, CB10, CB11, CB6, CB7, CB8, CB9, D, E, F,



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA22537	78	Continental Engines: A65, A75; C125-2; C145-2, 2H; C75, C85, C90; LTSIO-360-E, EB, KB; O-200-A, B; O-300-A, B, C, D; O-470-A; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA2265	54	Continental Engines A65; A75; C-125-2; C-145-2, 2H; GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, H, J, K, N; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G
SA22800	102	Continental Engines: A65; A75; C75; C85; C90; O-200-A, B; C-125; C-145-2, 2H; O-300-A, B, C, D
SA22949	1	Continental Engines: C-75; C-85; C-90; C125-2; C145-2, 2H; O-200-A, B; O-300-A, B, C, D
SA23410	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D
SA23411	137	Continental Engines: O-300-A, B, C, D; C145-2, 2H; C125-2
SA24024	1	Continental Engines: C-75; C-85; O-200; GO-300; C-90
SA24026	78	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; O-200-A, B; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB,
SA24029	1	Continental Engines: C-75; C-85; C-90; C-125-2; C145-2, 2H; O-200-A, B; O-300-A, B, C, D
SA24031	1	Continental Engines: C-90; C125-2; C145-2, 2H; O-200-A, B; O-300-A, B, C, D
SA24044	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA24047	1	Continental Engines: O-300; O-200; C-85; C-90; C-115; C-125; C-145



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA24122	1	Continental Engines: C-75; C-85; C-90; A-65; A-75; C-125-2; C145-2, 2H; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA24239	102	Continental Engines: O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; TSIO-470-B, C, D; IO-520-A, BA, C, D, E, F, J, K, L, M; TSIO-520-C, G, H, M, P, R, T, AF, BE, B, BB, D, DB, E, EB, J, JB, K, KB, L, LB,
SA24252	102	Continental Engines: A65; A75; C75; C85; C90; O-200-A, B
SA2437	137	Continental Engines: O-300-B, C, D; TSIO-470-B Spec 1, Spec 2, Spec 3; A65, 75; GO-300-A, C, D, E; C145-2, 2H; C125-2; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA2439	137	Continental Engines: A65, 75; C75, 85, 90; O-200-A, B; C-125-2; C-145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E; IO-346-A; E-165-2; E-185-1, 3, 8, 9, 11; E-225-4, 8; IO-360-A, C, D, G, H, J, K, AB, BB, CB, DB, HB, JB, KB; TSIO-360-A, AB, B, C, CB, D, DB
SA2441	77	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, L15, L19, L21, L22, M, N, N12, N3, P,
SA2471	77	Continental Engines: A65; A75; C145-2H; C75; C85; C90; IO-470-D, L, M, N10, N11, N12, P, S, U, V; IC 520-A, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, L; O-200-A, B; O-300-B; O-470-B, E, M, R, S, U; TSIO-470-B-2, B3, C, D; TSIO-520-AF, B, B
SA2472	54	Continental Engines: C90; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, F16, J, K, L, M, MB; IO-550-A, B, C, D
SA2473	54	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, K14, L, M, N, N3, P, R, S, U, V; IO-520-
SA24759	76	Continental Engines: C-125, 145; O-300 All Models
SA24764	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G,
SA24770	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C125-2; C145-2; O-300-A, C, D; E165-2; IO-346-A, A65, A75



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA24802	54	Continental Engines: E225-4, 8
SA24804	14	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75, 85, 90; O-200-A, B; O-300-A, B, C, D
SA24835	77	Continental Engines: IO-346; IO-470-C, D, E, F, F19, F3, F4, F7, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, BA, C, D, E, F, F12, F16, F3, F4, J, K, L, M, MB; IO-550-A, B, C, D, E, F, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, K17, L, L16, M, P, R, R14,
SA24856	76	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA24878A	101	Continental Engines: C125-2; C-75, 85, 90; IO-360-A, C, D, G, H, J, K; IO-520-BA, BB, C, CB; O-200-A, B, O-300-A, B, C, D; C-145-2, 2H; TSIO-520-B, BE, D, E, J, K, L, N, UB, VB, WB; GO-300-A, C, D, E; IO-550-A, B, C, G; TSIOL-550-A
SA25135	76	Continental Engines: O-470-B, E, M; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA25328	76	Continental Engines: C125-2; C145-2, 2H; O-300-A, B, C, D; TSIO-470-B1, B2, B3, C, D
SA25369	1	Continental Engines: C-75; C-85; A-65; C125-2
SA3364	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, B, C, D, E, F, G, GB, H, JB, KB, LB
SA3365	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, B, C, D, E, F, G, GB, H, JB, KB, LB
SA35019	76	Continental Engines: C75, C85, C90; O-200-A, B
SA350997	1	Continental Engines: O-470; TSIO-470



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA350998	54	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, B
SA352058	90	Continental Engines: E165-2; E185-1, 3, 8, 9; E225-4, 8
SA352059	76	Continental Engines: E165-2; E185-1, 3, 8, 9; E225-4, 8
SA352061	76	Continental Engines: E165-2; E185-1, 3, 8, 9; E225-4, 8
SA352062	76	Continental Engines: E165-2; E185-1, 3, 8, 9; E225-4, 8
SA352063	76	Continental Engines: E185-1, 8, 11; E225-8
SA352064	76	Continental Engines: E185-1, 8, 11; E225-8
SA352065	90	Continental Engines: E165-2; E185-1, 3
SA352066	76	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA352067	76	Continental Engines: O-470-7; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA352069	76	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA352179	90	Continental Engines: C125-2; C145-2, 2H; C75, C85, C90; GO-300-A, C; O-200-A, B; O-300-A, B, C



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA35562	43	Continental Engines: C125-2; C145-2, 2H; O-300-A, B, C, D
SA35563	43	Continental Engines: C125-2; C145-2, 2H; O-300-A, B, C, D
SA35636	14	Continental Engines: C75; C85; C90; C125; O-300-A; GO-300-A; O-200-A
SA3577	76	Continental Engines: A65, 75; C75, 85, 90; O-200-A, B
SA35897	1	Continental Engines: O-300; GO-300; C-75, 85; C-90; C-125; A-65; A-75; O-200; IO-360; TSIO-360
SA35923	76	Continental Engines: A65, A75; C75, C85, C90; O-200-A, B
SA35966	1	Continental Engines: IO-470-J, K; IO-346-A, B; O-470-A, B, E, J, 2, 4, 11, 15, 13A; FSO-470-A; E-185, 1, 3, 8, 9, 11; E-225-4, 8
SA35967	54	Continental Engines: E185-1, 3, 8, 9, 11; E225-4, 8
SA35971	54	Continental Engines: IO-346; IO-550-D, E, F, L; TSIO-470-B1, B2, B3, C, D; E165-2; E185-1, 3, 8, 9, 11; E 225-4, 8; O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, BA, C, D, E, G, H, J, K, L, M,
SA35972	35	Continental Engines: IO-346; TSIO-470-B1, B2, B3, C, D; O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA35985	76	Continental Engines: IO-470-B, C, E, H, J, M; LTSIO-360-E, EB, KB; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-360-A, AB, B, E, F, FB, G, GB, H, JB, KB, LB; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA36027	76	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA36050	76	Continental Engines: C125-2; C145-2, 2H; O-300-A, B, C, D
SA36066	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B
SA36100	76	Continental Engines: C125-2; C145-2, 2H; GO-300-A, C, D, E; O-300-A, B, C, D
SA36151	77	Continental Engines: IO-346; TSIO-470-B1, B3, C, D; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IC 520-A, BA, C, E, F, J, K, L, M, MB; TSIO-520-AF, B, C, D, E, G, H, M, P, R, J, K, L, N, UB, VB, WB; IO-550-A, B, C; O-470-K, L, R, S, U; A65; A75; C75
SA36151-L		Continental Engines: IO-346; TSIO-470-B1, B3, C, D; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IC 520-A, BA, C, E, F, J, K, L, M, MB; TSIO-520-AF, B, C, D, E, G, H, M, P, R, J, K, L, N, UB, VB, WB; IO-550-A, B, C; O-470-K, L, R, S, U; A65; A75; C75
SA36151-N		Continental Engines: IO-346; TSIO-470-B1, B3, C, D; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IC 520-A, BA, C, E, F, J, K, L, M, MB; TSIO-520-AF, B, C, D, E, G, H, M, P, R, J, K, L, N, UB, VB, WB; IO-550-A, B, C; O-470-K, L, R, S, U; A65; A75; C75
SA36170	1	Continental Engines: C125-2; C145-2; O-300-A, C, D
SA36171	1	Continental Engines: C125-2; C145-2, 2H; O-300-A, B, C, D
SA3920	1	Continental Engines: O-300; O-200; C-85; C-90; C-115; C-125; C-145
SA3921	1	Continental Engines: C-85; C-90; C-125; C-145
SA3923	1	Continental Engines: C-75
SA4001	29	Continental Engines: O-470-A, B, E, G, J, K, L, M, P, 4, 7B, 11, 13, 13A; IO-470-C, J, K; LIO-470-A; E185-13, 8, 9, 11; E225-4, 8



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA4003	35	Continental Engines: TSIO-470-B, C, D; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; O-470-A, B, E, G, J, K, L, M, P, R, S, U, 4, 7B, 13, 13A; LIO-470-A; E185-1, 3, 8, 9, 11; E225-4, 8
SA401507	77	Continental Engines: C125-2; C145-2; C75; C85; C90; GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, C, D, G, H, J, K; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V, V10, V2, V8; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L,
SA401804	54	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, H, J; IO-520-B, BA, BB, CB, M, MB; IO-550-A, B, C, G, L; O-200-A, A2, A23, A36, A57, B; O-300-A, B, C, D; O-470-B, G,
SA401814	78	Continental Engines: GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-P; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; LTSIO-360-E, EB, KB; O-470-B, E, P, R32; TSIO-360-A, AB, B, C,
SA401870	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F; IO-360-C, G; LTSIO-360-E, KB; TSIO-360-A, B, C,
SA401885	78	Continental Engines: A65; A75; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, DB, E, EB, F, J, JB, K, KB, L, LB, M, M
SA401893	102	Continental Engines: O-470-G, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; TSIC 470-B, C, D; IO-520-A, BA, C, D, E, F, J, K, L, M; TSIO-520-B, D, E, DB, EB, BE; GTSIO-520-C, D, F, H, K, L, M; TSIO-520-C, G, H, M, R, T
SA402044	78	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75; C85; C90; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; O-200-A, A57, B; O-300-A, B; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB; TSIO-520
SA402151	54	Continental Engines: C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; GTSIO-520-C, D, H, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, EB, FB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, R, S, U, V; IO-520-A, B, BA, BB, C, CB,
SA40644	1	Continental Engines: E-185-1; E-225-B
SA4577	90	Continental Engines: A65, A75; C75, C85, C90
SA4700	1	Continental Engines: O-470-A, E, G, J, K, L, R, M, P, 4, 7B, 11, 13, 13A; IO-470-C, J, K; LIO-470-A; E185-1, 3, 8, 9, 11; E225-4, 8



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA47000L	147	Continental Engines: O-470-U; IO-470-D, E, F, H, L, LO, M, N, S, U, V
SA47000LCK	147	Continental Engines: O-470-U; IO-470-D, E, F, H, L, LO, M, N, S, U, V
SA47000S	147	Continental Engines: O-470-G, K, L, M, P, R, S; IO-470-C, G, P, R
SA47000SCK	147	Continental Engines: O-470-G, K, L, M, P, R, S; IO-470-C, G, P, R
SA4701	1	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; O-470-A, B, E, G, J, K, L, M, P, R, S, U, 4, 7B, 11, 13, 13A; LIO-470-A; TSIO-470-B, C, D; E185-1, 3, 8, 9, 11; E225-4, 8
SA47030-P15	166	Continental Engine: O-470-G, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V
SA4705	63	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, T, U, V; O-470-A, B, E, G, J, K, L, M, P, R, S, U, 4, 7B, 11, 13, 13A; TSIO-470-B, C, D; E185-1, 3, 8, 9, 11; E225-4, 8
SA4706A	77	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; O-470-A, B, E, G, J, K, L, M, P, R, S, U, 4, 7B, 11, 13, 13A
SA4707	29	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8; O-470-A, E, G, J, 4, 7B, 11, 13, 13A, K, L, R, M, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; LIO-470-A; TSIO-470-B, C, D
SA4708	56	Continental Engines: O-470 and IO-470 Series
SA4709	35	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, T, U, V; O-470-A, B, E, G, J, K, L, M, P, R, S, U, 4, 7B, 11, 13, 13A; TSIO-470-B, C, D; LIO-470-A; TSIO-470-B, C, D; E185-1, 3, 8, 9, 11; E225-4, 8
SA5001	45	Continental Engines: IO-520-M; TSIO-520-M, N, P, R



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA5002	45	Continental Engines: 520-M, N, P, R
SA5003	36	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, BE, D, J, K, L, N, UB, VB, WB, AE, AF, C, CE, G, H, M, P, R, T, U, BB, DB, EB, JB, KB, LB, NB; GTSIO-520-C, D, F, G, H, K, L, M, N; TSIOL-550-A; LTSIO-520-AE;
SA5003A	54	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, BE, D, E, J, K, L, N, UB, VB, WB, AE, AF, C, CE, G, H, M, P, R, T, U, BB, DB, EB, JB, KB, LB, NB; GTSIO-520-C, D, F, G, H, K, L, M, N; IO-550-A, B, C, D, E, F, G, L; TS
SA5004	44	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, BE, D, E, J, K, L, N, UB, VB, WB, AF, C, CE, G, H, M, P, R, T, BB, CE, DB, EB, JB, U, KB, LB, NB; GTSIO-520-C, D, F, G, H, K, L, M, N; IO-550-A, B, C, D, E, F, G, L; TS
SA5004A	54	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, BE, D, E, J, K, L, N, UB, VB, WB, AE, AF, C, CE, G, H, M, P, R, T, U, BB, DB, EB, JB, KB, LB, NB; GTSIO-520-C, D, F, G, H, K, L, M, N; IO-550-A, B, C, D, E, F, G, L; TS
SA501867	78	Continental Engines: GO-300-D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C
SA515152	1	Continental Engines: O-470-13A, 15, 2, A, J, E, 11; E-185-1, 9, 11, 8, 3; E-225-4, 8; GSO-526-A; IO-346-A, B; IO-470-J, K
SA52000	147	Continental Engines: IO-520-A, B, BA, C, D, E, F, J, K, L, M, BB, CB, MB; IO-550-A, B, C; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB
SA52000-A1		Continental Engines: IO-520-A, B, BA, C, D, E, F, J, K, L, M, N, BB, CB, MB, NB; IO-550-A, B, C, D, F, G, L; TSIO-520-A, AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB; LTSIO-520-AE
SA520004	76	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA52000CK	147	Continental Engines: IO-520-A, B, BA, C, D, E, F, J, K, L, M, BB, CB, MB; IO-550-A, B, C; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB
SA520046	101	Continental Engines: IO-520-A, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, C, D, E, G, H, J, K, L, M, N, P, R, T, UB, VB, WB; GTSIO-520-C, D, F, H, K, L, M, N; IO-550-A, B, C, D, E, F, G, L; IO-346



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA5201	54	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-B, C, D, E, F, L; TSIO-52 B, C, D, E, G, H, J, K, L, M, N, P, R, T, BB, BE, CE, DB, EB, JB, KB, LB, NB, U, UB, VB, WB, AE, AF; GTSIO-520-C, D, F, G, H, K, L, M, N; LTSIO-52
SA520105	1	Continental Engines: IO-346; TSIO-470-B1, B2, B3, C, D; O-470-A, E, J, B, G, K, L, M, R, P; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, T, U, V; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA520106	1	Continental Engines: O-470; IO-470; E-185; E-225; IO-346; TSIO-470
SA520112	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F; A65, A75; E165-2; E185-1, 3, 8, 9, 11; E225-4,
SA520129	147	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, G; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB
SA5201C	147	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-B, C, D, E, F, L; TSIO-52 B, C, D, E, G, H, J, K, L, M, N, P, R, T, BB, BE, CE, DB, EB, JB, KB, LB, NB, U, UB, VB, WB, AE, AF; LTSIO-520-AE
SA5202	54	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-B, C, D, E, F, L; TSIO-52 B, C, D, E, G, H, J, K, L, M, N, P, R, T, BB, BE, CE, DB, EB, JB, KB, LB, NB, U, UB, VB, WB, AE, AF; GTSIO-520-C, D, F, G, H, K, L, M, N; LTSIO-52
SA5202C	147	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-B, C, D, E, F, L; TSIO-52 B, C, D, E, G, H, J, K, L, M, N, P, R, T, BB, BE, CE, DB, EB, JB, KB, LB, NB, U, UB, VB, WB, AE, AF; TSIO-520-AE
SA5203	18	Continental Engines: GTSIO-520
SA52030-P15	166	Continental Engine: IO-520-A, B, BA, C, D, E, F, J, K, L, M, BB, CB, MB; IO-550-A, B, C; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB
SA5205	54	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-B, C, D, E, F, L; TSIO-52 B, C, D, E, G, H, J, K, L, M, N, P, R, T, BB, BE, CE, DB, EB, JB, KB, LB, NB, U, UB, VB, WB, AE, AF; GTSIO-520-C, D, F, G, H, K, L, M, N; LTSIO-52
SA5205A	95	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-B, C, D, E, F, L; TSIO-52 B, C, D, E, G, H, J, K, L, M, N, P, R, T, BB, BE, CE, DB, EB, JB, KB, LB, NB, U, UB, VB, WB, AE, AF; GTSIO-520-C, D, F, G, H, K, L, M, N; LTSIO-52



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA5207	63	Continental Engines: IO-520-A, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, BB, C, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, U, UB, VB, WB
SA5208	66	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, BE, C, D, J, K, L, N, M, P, UB, VB, WB, AF, C, CE, G, H, R, T, U, V, AE, BB, DB, EB, VB, WB, JB, KB, UB, LB, NB; GTSIO-520-C, D, F, H, K, L, M, N; IO-550-A, B, C, D, E,
SA5209	54	Continental Engines: IO-346; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, BE, D, E, J, K, L, N, M, P, UB, VB, WB, AF, C, CE, G, H, R, T, U, BB, DB, EB, JB, KB, LB, NB; GTSIO-520-C, D, F, H, K, L, M, N; IO-550-A, B, C, D, E, F, G, L; T
SA5209A	54	Continental Engines: IO-346; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, BE, D, E, J, K, L, N, UB, VB, WB, AF, C, CE, G, H, M, P, R, T, U, BB, DB, EB, JB, KB, LB, NB; GTSIO-520-C, D, F, G, H, K, L, M, N; IO-550-A, B, C, D, E, F, G, L
SA524818	54	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, WB; TSIOL-550-A
SA530011	76	Continental Engines: C125-2; C145-2, 2H; O-300-A, B, C, D
SA530019		Continental Engines: A65, A75; C75, C85, C90; O-200-A, B
SA530058	1	Continental Engines: A-65; A-75; C-75; C-85; C-90; O-200-A, B
SA530162	76	Continental Engines: A65, A75; C125-2; C145-2, 2H; C75, C85, C90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA530162-S	76	Continental Engines: A65; A75; C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA530192	1	Continental Engines: C125; C145-2, 2H; C90; O-200-A, B; O-300-A, B, C, D
SA530213	38	Continental Engines: C-75; C-85; C-90; O-200; C-125; C-145; O-300; GO-300; IO-360; TSIO-360; LTSIO-360



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA530340	76	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA530341	76	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA530346	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-D, E, F, G, L, L15, L19, L21, L22, M, N12, P, R, S, U, V, V6; IO-520-A, C, CB, D, D10, D15, E, E3, E6, F, F7, J, K, L, M, MB; IO-550-A, C, D, E, F, G, L; LTSIO-520-AE, AE3, O-470-A, B,
SA530348		Continental Engines: C145-2, 2H; C90; O-200-A, B; O-300-A, B, C, D
SA530367	1	Continental Engines: IO-346; IO-470-J, K; LTSIO-520-AE; O-470-A, E, J; TSIO-520-AE; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA530383	1	Continental Engines: IO-470-C, G, J, K, P, R; O-470-A, B, E, G, J, K, L, M, P, R; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA530386	1	Continental Engines: O-470; IO-470; E-185, E-225; GSIO-470; TSIO-470
SA530462	1	Continental Engines: IO-470-J, K; O-470-A, E, J
SA530516	14	Continental Engines: O-300-B
SA530523	76	Continental Engines: C145-2H; O-300-B
SA530642	76	Continental Engines: A65, A75; C125-2; C145-2, 2H; C75, C85, C90; O-300-A, B, C, D
SA530658	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA530828		Continental Engines: C-75, 85, 90, 125, 145; E-233, E-236; O-200; E-252, E-253; O-300-A, B, C, D
SA530829		Continental Engines: C-75, 85, 90, 125, 145; E-233, E-236; O-200; E-252, E-253; O-300-A, B, C, D
SA530830	3	Continental Engines: C125-2; C145-2, 2H; C75; C85; C90; O-200-A, B; O-300-A, B, C, D
SA530844	1	Continental Engines: O-470; IO-470; E-225; FSO-470; TSIO-470
SA530851	1	Continental Engines: C125-2; C145-2, 2H; C90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA530917	90	Continental Engines: C125-2; C145-2, 2H; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO 360-E, EB, KB; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H; GO-300-A, C, D, E
SA530928	76	Continental Engines: A65, A75; C125-2; C145-2, 2H; C75, C85, C90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA530940	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F; A65, A75; E165-2; E185-1, 3, 8, 9, 11; E225-4,
SA531001	54	Continental Engines: C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, C, D, G, H, J, K; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, L12, L13, M
SA531003	38	Continental Engines: C-75; C-85; C-90; O-200; E-165; E-185; E-225; C-125; C-145; O-300; GO-300; IO-360; TSIO-360; LTSIO-360; IO-346; IO-520; TSIO-520; GTSIO-520
SA531015	51	Continental Engines: C-145-2, 2H; O-300-A, E
SA531128	1	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA531178	54	Continental Engines: GTSIO-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L;
SA531378	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-D, L, M, P, U, V; IO-520-C, CB, E, M, MB IO-550-A, B, C, E; O-470-B, E, M, R, S, U; TSIO-470-B2, B3, C, D; TSIO-520-B, BB, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, WB; TSIOL-550-A
SA531608	1	Continental Engines: GO-300-A, C, D, E
SA532125	1	Continental Engines: O-470-2
SA532126	1	Continental Engines: O-470-2
SA532129	1	Continental Engines: O-470-2, 15, A, E, J; IO-470-J, K; E165-2; E185-1, 3, 8, 9, 11; IO-470-J, K; E225-4, 8; FSO-470-A
SA532200	102	Continental Engines: E-165 Series; E-185 Series; E-225 Series; O-470 Series; IO-470 Series; TSIO-470 Series
SA532432	77	Continental Engines: C125-2; C145-2; 2H; C75; C85; C90; GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, A6, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D,
SA532509	76	Continental Engines: O-470-11
SA532518	76	Continental Engines: O-470-4, 13
SA532519	76	Continental Engines: O-470-4, 11, 13
SA532520	90	Continental Engines: O-470-4, 13



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA533355	76	Continental Engines: C75; C85; C90; IO-520-B, BA, BB, C, CB, MB; IO-550-G; O-200-A, B; TSIO-360-A, B, C, D, H, JB; TSIO-520-B, B10, B12, B2, BB, BB10, BB12, BE, D, DB, E, E10, E2, E4, E9, EB, EB10, J, J2, J4, JB, JB10, JB12, JB2, JB4, K, K2, KB, KB2, KB4
SA533399	1	Continental Engines: C-75; C-85; C-90; C-125; C-145; O-200; E-165; E-185; E-225; O-300-A, B, C, D; GO-300-A, C, D, E
SA534079	76	Continental Engines: O-470-4, 13
SA534316	76	Continental Engines: O-470-A, P
SA534610	90	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S,
SA534655	51	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-C, D, E, F, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, C, CE, G, H, M, P, R, T
SA534685	54	Continental Engines: IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB,
SA534715	77	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-C, D, E, F, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, C, G, H, M, P, R
SA534740	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U;
SA534743	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-47
SA534750	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G,
SA534857	95	Continental Engines: IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, L; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G,



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA534857-S	95	Continental Engines: IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, L; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G.
SA534863	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S.
SA534895	4	Continental Engines: IO-470-J, K; O-470-A, E, J; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA534940	76	Continental Engines: GTSO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF
SA534941	76	Continental Engines: GTSIO-520-C, D, F, H, K; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U; O-470-A, B, E, G, J, K, K5, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-C, G, H
SA535008A	101	Continental Engines: IO-520-A, BA, BB, F, J, K, L; TSIO-520-AF, C, CE, D, G, H, M, P, R, T, UB; GTSIO 520-L, M, N; IO-470-C, E, F, G, H, J, K, N, R, S; O-470-A, G, J, K, L, P, R, S, U; IO-550-D, E, F, G, L; IO-346
SA535057	76	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA535091-.62		Continental Engines: A65; A75; C125-2; C145-2, 2H; GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, C, D, G, H, J, K, AB, CB, DB, GB, HB, JB, KB; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; LTSIO-360-E, KB; LTSIO-520-AE; O-300-A, B, C, D
SA535324	76	Continental Engines: A65; C125-2; C145-2H; C75, 85, 90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA535634	77	Continental Engines: GTSIO-520-L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B2, B3, C, D; TSIO-
SA535661	14	Continental Engines: IO-520-A, D, E, F, J, K, L; TSIO-470-B, C, D; TSIO-520-AF, C, CE, G, H, M, P, R, T; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-550-D, E, F, L
SA535666	49	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-520-A, C6, CB6, D, E, F, J, K, L; LTSIO 520-AE; O-470-B, E, G, L, M, P, R32; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, C, CE, G, H, M, P, R, T; IO-470-C, D, E, F, G, H, J, K, L, M, N, P.



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA535668	102	Continental Engines: O-470-M; IO-470-D, L, U, V; TSIO-470-B, C, D; IO-520-A, Specs. 9, 12, 7, 22, 24, 30, 34; F Specs. 2, 9, 11, 13, 17; L Specs. 3, 7; TSIO-520-C, G, H, M, P, R
SA535823	102	Continental Engines: O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; TSIO-520-C, G, H, M, P, R, T, AF, AE, CE; GTSIO-520-C, D, F, H, K, L, M, N
SA535885	76	Continental Engines: GTSIO-520-L, M, N; IO-470-D, L, M, P, U, V; IO-520-C, CB, E, M, MB; IO-550-A, B, C, E; O-470-B, E, M; TSIO-470-B2, B3, C, D; TSIO-520-B, BB, E, EB, J, JB, K, KB, L, LB, N, NB, VB, WB; TSIO-550-A
SA535933	77	Continental Engines: IO-470-C, D, E, F, M, P, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, F; O-470-A, B, E, G, J, K, L, M, R, S, U; TSIO-520-T
SA536033	1	Continental Engines: O-470; GIO-470; GSO-526; IO-470; IO-520; GSIO-520; FSO-526; FSO-470; TSIO-470; TSIO-520
SA536379	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1,
SA536410	102	Continental Engines: IO-346-A; O-470-A, E, J; IO-470-J, K
SA536410	102	Continental Engines: IO-346-A; O-470-A, E, J; IO-470-J, K
SA536413	76	Continental Engines: IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, F, L; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G, H,
SA536563	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B
SA536634	76	Continental Engines: O-470-4, 13; IO-346; E-165-2; E-185-1, 3, 8, 9, 11; E-225-4, 8
SA536740	90	Continental Engines: IO-346; E-165-2; E-185-1, 3, 8, 9, 11; E-225-4, 8



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA536799	76	Continental Engines: O-470-4, 13
SA536938	1	Continental Engines: O-470-A, B, E, J, K, L, M, N, P, R, 2, 4, 11, 13A; E-185-1, 3, 8, 9, 11; E-225-8; IO-470-J, K; GSO-470-A
SA537019	54	Continental Engines: GTSIO-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO
SA537064	1	Continental Engines: IO-470-11
SA537282	76	Continental Engines: IO-470-D, F19, F23, F3, F4, F5, F7, L, M, S2, S8; IO-520-A, D, E, F, J, K, L; LTSIO-520-AE; O-470-B, J11, K17, L16, M, R14, R6; TSIO-470-B1; TSIO-520-AE
SA537296	54	Continental Engines: IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB,
SA537401	1	Continental Engines: O-470-A, E, J, K, L
SA537728	78	Continental Engines: IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-S; IO-520-A, F, J, K, L; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, C6, CB6, D, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB; TSIO-520-AF, C, CE, G, H, M, P, R
SA537745	76	Continental Engines: GTSIO-520-C, D, F; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1; TSIO-520-AE, AF, C, CE, G, H, M, P, R, T
SA537749	76	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, C, G, H, M, P, R
SA537848	1	Continental Engines: O-470; IO-470
SA537870	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F; A65, A75



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA538185	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, F; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, C, G, H, M, P, R, T
SA538304	101	Continental Engines: IO-520-A, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, C, CE, D, E, G, H, J, K, L, M, N, P, R, T, UB, VB, WB; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; O-470-B, G, K, L, M, P, R, S, U; IO-
SA538468	77	Continental Engines: IO-470-D, E, G, L, M, P, R, U, V; IO-520-C, CB, E; IO-550-C, E; O-470-B, E, M
SA538556	137	Continental Engines: C75, 85, 90; O-200-A, B
SA538684	1	Continental Engines: GO-300-A, C, D, E; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA538804	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, A
SA538999	78	Continental Engines: C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C; GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E,
SA539058	78	Continental Engines: GO-300-D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, N3, P, R, S, U, V, V10; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-55
SA539467	1	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; O-470-A, B, E, G, J, K, L, M, P, R, S, U, 4, 13, 13A; TSIO-470-B1, B2, B3, C, D
SA539473	1	Continental Engines: O-470; IO-470; FSO-470; TSIO-470
SA539568	1	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; O-470-B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, C, G, H, M, P, R
SA539740	77	Continental Engines: IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, C, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, N



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA539800	1	Continental Engines: IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E; IO-550-A, B, C, D, E, F, G, L; O-300-D; O-470-B, E, G, J, K, L, M, P, R, U; TSIO
SA539814	1	Continental Engines: O-470; IO-470
SA539840	90	Continental Engines: A65, A75; C125-2; C145-2, 2H; C75, C85, C90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA539942	54	Continental Engines: GTSIO-520-C, D, H, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO 520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, D, E, F, G, L; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G
SA539988	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; LTSIO-520-AE; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, U, UB, VB, WB;
SA539988V	147	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; LTSIO-520-AE; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, U, UB, VB,
SA5484	76	Continental Engines: C75; C85; C90; O-200-A, B
SA625065	1	Continental Engines: O-470; IO-470; TSIO-470
SA625142	49	Continental Engines: IO-346; IO-470-J, K; LTSIO-520-AE; O-470-A, E, J; TSIO-520-AE; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA625147	1	Continental Engines: LIO-470-A; IO-470-C, G, R, P; O-470-G, 15
SA625303	76	Continental Engines: IO-470-C, D, E, F, F5, G, H, J, L, M, N, R, S; IO-520-A, D, E, F, J, K, L; O-470-A, B, E, G, J, K, K14, L, M, P, R, S, U; LTSIO-520-AE; TSIO-470-B1; TSIO-520-AE
SA625393	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, U,



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA625457	54	Continental Engines: GTSIO-520-C, D, H, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M; IO-550-B, C, D, E, F, L; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, C, CE, E, EB, G, H, M, P, R,
SA625615	161	TCM Engines: O-470-B, G, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; TSIO-470-B, C, D; IO-520-A, BA, C, D, E, F, J, K, L, M; TSIO-520-B, D, E, J, K, L, M, N, UB, VB, WB
SA625821	1	Continental Engines: E-185; E-225; O-470-A, E, J, G, K, L, N
SA625957	78	Continental Engines: GO-300-A, C, D, E; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA625958	1	Continental Engines: C125-2; C145-2, 2H; C75; C-85; C-90; GO-300-A, C, D, E; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; O-200-A, B; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB,
SA625961	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA625966	90	Continental Engines: IO-470-C, D, D12, D15, D19, D27, D30, D42, D44, D50, D52, E, F, F18, F26, G, H, J, K, K14, L, N, P, R, U, V; IO-520-A, A12, A9, D, D22, D24, D27, D30, D34, D4, D40, E, E2, E6, E7, F, F11, F13, F17, F2, F5, F6, F7, F9, J, K, L, L3, L7
SA626140	14	Continental Engines: GO-300-A, C, D, E; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, H, J, K, L, M, N, P, R, S, U, V; LTSIO-360-E, EB, KB; O-470-4, 11, 15, A, B, E, G, J, K, L, M, P, R, S, U; TSIO-360-A, AB, B, C, CB
SA626341	76	Continental Engines: IO-470-D, D12, D15, D19, D27, D30, D42, D44, D50, D52, F18, F26, K, L, L11, L12, L15, L16, L19, L20, L21, L22, L5, L8, L9, U, V; IO-520-A12, A7, A9, D22, D24, D27, D30, D33, D34, D35, D4, D40, E2, E6, E7, F11, F13, F17, F2, F5, F6, F
SA626342	76	Continental Engines: IO-470-D, D12, D15, D19, D27, D30, D42, D44, D50, D52, F18, F26, K14, L, L11, L12, L15, L16, L19, L20, L21, L22, L5, L8, L9, U, V; IO-520-A12, A7, A9, D22, D24, D27, D30, D34, D4, D40, E2, E6, E7, F11, F13, F17, F2, F5, F6, F7, F9, L
SA626348	1	Continental Engines: GSO-526-A; GSIO-520-C, D; GIO-470-A; TSIO-470-B, C, D; TSIO-520-A, B, C, D, E
SA626487	102	Continental Engines: C-125-2; C-145-2, 2H; GO-300-A, C, D, E; IO-360-A, C, D, G, H, J, K; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; LTSIO-360-E, KB; LTSIO-520-AE; O-300-A, B, C, D; O-470-A, B, E



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA626540	1	Continental Engines: O-470; IO-470; LIO-470; IO-346; IO-520; E-185, E-225
SA626543	90	Continental Engines: C125-2; C145-2, 2H; C75, C85, C90; GO-300-A, C, D, E; IO-360-A6; O-200-A, B; O-300-A, B, C, D
SA626564		Continental Engines: GO-300-A, C, D, E
SA626566	51	Continental Engines: GO-300-A, C, D, E
SA626740	14	Continental Engines: O-470-G, P; IO-470-C, D, E, F, G, H, J, K, L, M, N, R, S, U, V
SA626741	1	Continental Engines: O-470-G, P; IO-470-C, D, E, F, G, H, J, K, L, N, R, S, U, V
SA626813	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; TSIO-360-MB; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF,
SA626879-1	137	Continental Engines: TSIO-520-C, G, H, M, P, R, T, AF, CE, D, UB, B, E; IO-520-A, BA, BB, C, CB, D, E, F, J, K, L, M; IO-470-C, H, J, D, E, G, P, R, F, K, N, L, M, S; IO-550-B, C; GTSIO-520-C, D, H
SA626889	54	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-G; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J,
SA626983	76	Continental Engines: O-200-A, B
SA626992	27	Continental Engines: O-470-K, L, R
SA627246	1	Continental Engines: A65; A75; C-75; C-85; C-90; O-200



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA627330	1	Continental Engines: C-90; C-145; O-200; O-300; GO-300
SA627336	1	Continental Engines: C145-2, 2H; C-90-8F, 8FJ, 12F, 12FJ, 14F; O-200-A; O-300-A, B, C, D; GO-300-A, C, D, E
SA627368	76	Continental Engines: IO-470-D, E, G, L, M, P, R, U, V; IO-520-C, CB, E; IO-550-C, E
SA627429	90	Continental Engines: A65, A75; C125-2; C145-2, 2H; C75; C85; C90; IO-470-J, K; LTSIO-520-E; O-200-A, B; O-300-A, B, C, D; O-470-A, E, J; TSIO-520-AE; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8, 11
SA627433	78	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, D11, D15, D2, E, F, J, K, L; IO-550-D, E, F, L; LTSIO-360-E, EB, KB; O-470-
SA627480	1	Continental Engines: IO-470-D, E, F, G, H, L, M, N, P, S, T, U, V; O-470-K, L, R; TSIO-470-B, C, D; GIO-470-A
SA627496	77	Continental Engines: GO-300-A, C, D, E; GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, C, D, G, H, J, K; IO-470-D, L, U, V; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, D, E, F, G; LTSIO-360-E, KB; LTSIO-520-AE2, AE3; O-470-M; TSIO-360-A, B, C, D, E, F,
SA627693	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA627722	1	Continental Engines: IO-346; IO-520; GSIO-520; TSIO-520
SA627731	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA627738	1	Continental Engines: IO-470
SA627795	1	Continental Engines: O-470-G, P; IO-470-C, D, E, F, G, H, J, K, L, M, N, R, S, U, V



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA627993	76	Continental Engines: GO-300-D, E; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; O-300-D; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA628109	54	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AF, B, BB, BE, C, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R,
SA628136	1	Continental Engines: TSIO-470
SA628260	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, U, UB, VB, WB; O-470-B, G, K
SA628309	1	Continental Engines: C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; O-200-A, B; O-300-A, B, C, D
SA628321	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-D, F, L, M, MB; IO-550-A, B, C, D, F, G, L; LTSIO-360-E, EB, KB; O-470-A, B, E, G,
SA628488	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-550-G; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, C, CE, D, E, G, H, J, K, L, M, N, P, R, T, U,
SA628555-1	137	Continental Engines: TSIO-520-B, E, D
SA628555-16		Continental Engines: O-200-A, B
SA628555-3	137	Continental Engines: GTSIO-520-F, K; TSIO-520-K, J, N
SA628556	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-550-G; LTSIO-360-E, KB; LTSIO-520-AE; TSIO-360-A, B, C, D, E, F, GB, H, JB, KB, LB, MB; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, EB, G, H, JB, K, KB, L, LB, M, N, NB, P
SA628572	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; TSIO-470-B1, B2; TSIO-520-B, BB, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; TSIOL-550-A



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA628750	1	Continental Engines: O-470; TSIO-520; IO-470; IO-520; TSIO-470; IO-360
SA628754	1	Continental Engines: O-470; IO-470
SA628939	1 & 16	Continental Engines: O-300; C-145; O-470
SA628940	1	Continental Engines: O-300; O-200; GO-300; C-90; C-145
SA628975	48	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N
SA628978	14	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; GIO-470
SA628985	1	Continental Engines: IO-470-D, E, F, G, L, M; TSIO-470-B
SA629016	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N
SA629077	54	Continental Engines: GTSIO-520-C; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2,
SA629104	54	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, B
SA629116	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N
SA629117	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, G; LTSIO-520-AE; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB,



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA629159	76	Continental Engines: GTSIO-520-C; TSIO-470-B1, B2, B3, C, D
SA629196	137	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; TSIO-360-E, F, GB, KB, LB, MB, EB, FB; LTSIO-360-E, EB, KB
SA629202	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, R, S, U;
SA629340	54	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AF, B, BB, BE, C, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R,
SA629401	1	Continental Engines: IO-346-A, B; IO-520-A, B, C, D, E, F; TSIO-520-A, B, C, D, E; GTSIO-520-C
SA629404	1	Continental Engines: C125-2; C145-2, 2H; C75; C85; C90; O-300-A, B, C, D; O-200-A, B
SA629436	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; TSIOL-550-A
SA629609	14	Continental Engines: O-300-A
SA629690	45	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, GB, H, HB, JB, KB, LB, MB
SA629702	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA629706	14	Continental Engines: IO-360-A, C, D; TSIO-360-A, B
SA629707	14	Continental Engines: GO-300-A, C, D, E



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA629711		Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO 360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA629747		Continental Engines: IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, WB; TSIOL-550-A
SA629848	1	Continental Engines: IO-470
SA629891	1	Continental Engines: GIO-470; GSIO-520; IO-346; IO-520; TSIO-520
SA629925	76	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO 360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA630046	1	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; TSIO-520-B, BB, C, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB; TSIO-520-BE, CE;
SA630046-1	101	Continental Engines: IO-520-A, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-B, C, D, E, G, H, J, K, L, M, N, P, R, T, UB, VB, WB; GTSIO-520-C, D, F, H, K, L, M, N; IO-550-A, B, C, D, E, F, G, L; IO-346
SA630261	14	Continental Engines: GO-300-A, C, D, E; GIO-300; C145-2, 2H; O-300-A, B, C, D; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; GTSIO-520-C, D, F, H, K, L, M, N; O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K,
SA630262	1	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; TSIO-360-AB, CB, DB, FB, HB; LTSIO-360-EB
SA630286	76 & 137	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-550-G; LTSIO-360-E, EB, KB; LTSIO-520-AE; TSIO-360-A, AB, C, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB; TSIO-520-AE, BE
SA630350	76	Continental Engines: IO-470-S; IO-520-A, F, J, K, L; IO-550-F, L; TSIO-520-AF, C, CE, G, H, M, P, R
SA630365	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO 360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, GB4, H, HB, JB, KB, LB



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA630464	1	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U V; TSIO-470-B1, B2, B3, D; TSIO 520-AE, C, G, H, M, P, R, T; IO-520-A, D, E, F, J, K, L; O-470-A, E, G, J, K, L, P, R; GTSIO-520-C, D, F, H, K, L, M, N
SA630591	1	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-B, BB, C, D, DB, E, EB, G, H, J, JB, K, KB, L,
SA630678	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO 360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA630680	54	Continental Engines: IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; LTSIO-360-E, EB, KB; O-300-D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB; TSIO-520-B,
SA630681	54	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, WB; TSIOL-550-A
SA630692		Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO 360-A, AA, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA630693	54	Continental Engines: O-470-S, U; IO-520-BA, C, M; TSIO-520-B, C, E, H, J, K, L, M, N, P, R, T, U, VB, WB
SA630717	14	Continental Engines: IO-360-A, C, D
SA630742	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO 360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA630752	1	Continental Engines: IO-346-A, B; TSIO-520-A, B, C, D, E; GSIO-520-C; IO-520-A, B, C, D, E, F
SA630753	1	Continental Engines: IO-346-A, B; TSIO-520-A, B, C, D, E; GSIO-520-C; IO-520-A, B, C, D, E, F
SA630763	76	Continental Engines: IO-346; IO-520-B, BA, C, M, MB; TSIO-520-B, D, E, J, K, L, N



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA630789	1	Continental Engines: IO-520
SA630817	90	Continental Engines: GTSIO-520-C
SA630817-1	90	Continental Engines: TSIO-520-K
SA630824	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-550-G; TSIO-520-BE
SA630826	24	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, S, U, V; IC 520-A, B, BA, C, D, E, F, J, K, L, M; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AE, AF, B, C, D, E, G, H, J, K, L, M, N, P, R, T
SA630849	76	Continental Engines: IO-520-B, BA, BB, M, MB; TSIO-520-B, BB, BE, E, EB, J, JB, K, KB, L, LB, N, NB, VB, WB
SA630892	76	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, V, VB, WB; TSIOL-550-A
SA630895	101	Continental Engines: IO-520-BA, BB, C, CB, M, MB; IO-550-A, C, G; IO-346
SA630899	54	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, WB; TSIOL-550-A
SA630916	76	Continental Engines: IO-346; IO-520-BA, C, M
SA630966	54	Continental Engines: O-200; TSIO-360-F; IO-520-C, M, BA; TSIO-520-B, D, E, J, K, L, N, T, U, VB, WB; GTSIO-520-F, K
SA630979-9	137	Continental Engines: TSIO-360-MB, E, F, KB, GB, LB, B, C, D, H, JB, AB, CB, DB, EB, FB, HB, A; LTSIO 360-E, EB, KB; TSIO-520-D, B, E, BB, EB, DB, J, JB, N, NB, K, KB, L, LB, WB, UB, VB, C, G, H, M, P, R, T, AE, CE; GTSIO-520-C



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA630993	137	Continental Engines: GTSIO-520-C
SA630993-1	137	Continental Engines: GTSIO-520-D, F, H, K, L, M, N
SA631034	76	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; TSIOL-550-A; IO-550-B, C
SA631059	76	Continental Engines: IO-520-B, BA, BB, M, MB; IO-550-A, B, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; TSIOL-550-A
SA631088	49	Continental Engines: IO-346; IO-520-BA, C, M; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, WB; TSIOL-550-A
SA631250	1	Continental Engines: GTSIO-520-C
SA631263	54	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C; TSIO-520-B, BB, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, W, WB; TSIOL-550-A
SA631475	1	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB
SA631481	1	Continental Engines: IO-470; GIO-470; TSIO-470
SA631496	31	Continental Engines: TSIO-470-B1, B2, B3, C, D; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8; IO-346-A; O-470 A, B, E, G, J, K, L, M, P, R, S, U; IO-520-A, BA, C, D, E, F, J, K, L, M, BB, CB, MB; TSIO-520-AF, AE, B, BB, C, CE, D, DB, E, EB, G, H, J, JB, K, KB,
SA631501	1	Continental Engines: IO-470-D, E, F, H, L, M, N, S, T, U, V; TSIO-470-B, C, D; GIO-470-A
SA631520	54	Continental Engines: IO-520-M, BA; TSIO-520-B, D, K, L, M, N, P, R, T, U, VB, WB



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA631521	54	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AE, AF, B, BB, BE, C, CE, D,
SA631544	90	Continental Engines: IO-470-C, D, E, F, R, S, U, V; O-470-B, G, K, L, M, P, R, S, U
SA631554		Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N
SA631654	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA631685	76	Continental Engines: GTSIO-520-L, M, N; IO-470-V; IO-520-A, D, E, F, J, K, L; LTSIO-520-AE; TSIO-520-AE, AF, CE, M, P, R, T
SA631727	1	Continental Engines: TSIO-470; GIO-470; IO-470
SA631729	1	Continental Engines: IO-520; GSIO-520; TSIO-520
SA631730	1	Continental Engines: GTSIO-520; IO-520; TSIO-520
SA631731	1	Continental Engines: IO-520
SA631794	36	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N
SA631808	91	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N
SA631815	24	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; TSIO-520-BE



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA631845	95	Continental Engines: IO-470-U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-U; TSIO-520-AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB; TSIOL-550-A
SA631928	137	Continental Engines: IO-360-D19, D20, D25, D30, D31, D32, D34, DB19, DB20, DB25, DB30, DB31, DB32, HB, J, JB, K, KB; TSIO-360-GB, LB, MB; IO-520-A, D, E, F, J, K, L; IO-470-F23, F26, F7, S; O-470-R, S, U; IO-550-D, E, F, L; LTSIO-520-AE; TSIO-520-AE, AF,
SA631991	39	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, GB, H, HB, JB, KB, LB, MB
SA632039	1	Continental Engines: IO-470-D, E, F, L, M, N, V; TSIO-470-B, C, D
SA632050	97	Continental Engines: O-200-A, B; IO-360-A, C, D, G, H, J, K, A5, A6, C5, C6, C7, D6, D7, D8, D9, D11, D12, D15, D19, D20, D21, D22, D23, D25, D26, D30, D31, D32, D33, D34, G2, H2, H3, H4, H5, H6, H7, J2, J3, J4, J5, K2, K3, K4; TSIO-360-A, B, A3
SA632085	102	Continental Engines: A65; C75; C85; C90; IO-346; IO-470-C, E, F, G, H, J, K, N, R, S; IO-520-A, B, BA, BB, D, F, J, K, L; IO-550-D, F, G, L; O-470-A, G, P, R, S; TSIO-520-AF, C, CE, D, DB, G, H, M, P, R, T, UB
SA632092-4	54	Continental Engines: IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, WB; TSIOL-550-A
SA632120A	98	Continental Engines: IO-346-A; IO-520-C, M, CB, MB; IO-550-A, B, C, G; TSIO-520-B, D, E, J, K, L, N, BB, DB, EB, JB, KB, LB, NB, UB, VB, WB; TSIOL-550-A; GTSIO-520-C, D, F, H, K, L, M, N
SA632141	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA632156	14	Continental Engines: IO-360-A, C, D; TSIO-360-A, B
SA632157	14	Continental Engines: IO-360-A, C, D; TSIO-360-A, B
SA632248	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-550-G; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB; TSIO-520-BE



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA632266	76	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; TSIOL-550-A
SA632310	76	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO 360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA632310-S		Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO 360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA632372	76	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, E, G, H, J, K, N, R, S; LTSIO-360-E, EB, KB; O-470-G, K14, L, P, R, S, U; TSIO-360-A, AB, B, C, CB, D, DB, E, FB, G, GB, H, HB, JB, KB, LB, MB
SA632443A-4	96	Continental Engines: TSIO-470-B, C, D; TSIO-520-B, D, E, J, K, L, N, UB, VB, WB, BB, DB, EB, JB, KB, LB, NB, C, G, H, M, P, R, T, AF, AE, CE; LTSIO-520-AE; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-B, BA, BB, C, CB, M, MB, A, D, E, F,
SA632443A-6	96	Continental Engines: IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIOL-550-A; TSIO-520-B, BB, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB
SA632459	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-550-G; TSIO-520-BE
SA632459-S		Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-550-G; TSIO-520-BE
SA632585	1	Continental Engines: TSIO-520
SA632655	76	Continental Engines: IO-346
SA632710	76	Continental Engines: GTSIO-520-D, H; TSIO-520-B, BB, CE, D, DB, E, EB, J, JB, K, KB, N, NB, U, UB, VB
SA632837	90	Continental Engines: A65, A75; C75, C85, C90; C125-2; C145-2, 2H; IO-346; IO-470-J, K; O-200-A, B; O-470-A, E, J; O-300-A, B, C, D



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA632857	14	Continental Engines: IO-360-C, D
SA632885	14	Continental Engines: IO-360-C, D
SA632892	95	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; TSIOL-550-A
SA632893	95	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; TSIOL-550-A
SA632932	52	Continental Engines: O-470-K, L, R
SA632945	76	Continental Engines: LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB; IO-360-A, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB
SA633106	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA633136	48	Continental Engines: O-470-A, B, E, J, K, L, M, R, S, U
SA633141	1	Continental Engines: A65, A75; C75; C85; C90; O-200-A, B
SA633240	76	Continental Engines: C75; C85; C90; IO-520-B, BA, BB, C, CB, M, MB; O-200-A, B; TSIO-520-B, B10, B12 B2, BB, BB10, BB12, D, DB, E, E10, E2, E4, E9, EB, EB10, J, J2, J4, JB, JB10, JB12, JB2, JB4, K, K2, KB, KB2, KB4, L, LB, N, N10, N12, N14, N16, N2, N4,
SA633317	1	Continental Engines: O-470-K, L, R
SA633358	78	Continental Engines: LTSIO-360-E, EB, KB; TSIO-360-E, EB, F, FB, GB, GB4, KB, LB; TSIO-520-T



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA633398	1	Continental Engines: A65, A75; C75, C85, C90; O-200-A, B
SA633399	1	Continental Engines: A-65; C-85; C-90
SA633542	78	Continental Engines: LTSIO-360-E, EB, KB; TSIO-360-B, C, CB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB
SA633602	78	Continental Engines: C125-2; C145-2, 2H; IO-360-A, AB, B, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB LTSIO-360-E, EB, KB; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, J, JB, K, KB, LB, MB
SA633610	78	Continental Engines: C125-2; C145-2, 2H; IO-360-A, AB, B, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB LTSIO-360-E, EB, KB; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, J, JB, K, KB, LB, MB
SA633611	78	Continental Engines: C125-2; C145-2, 2H; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO 360-E, EB, KB; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, J, JB, K, KB, LB, MB
SA633752	76	Continental Engines: IO-360-C, CB, G, GB; TSIO-360-A, AB, D, DB, LB
SA633834	1	Continental Engines: GTSIO-520-D
SA633845	78	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-346; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G,
SA633958-3	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; LTSIO-360-E, EB, KB; LTSIO-520-AE; TSIO-360 A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K,
SA633958-5	78	Continental Engines: GTSIO-520-C, D, H, L, M, N; LTSIO-360-E, EB KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB; TSIO-520-AF, B, BB, C, D, DB, E, EB, G, H, L, LB, M, P, R, UB, WB
SA633976	78	Continental Engines: GO-300-A, C, D, E; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA634033	14	Continental Engines: IO-520-A, B, C, D, E, F; TSIO-520-B, C, D; GTSIO-520-C
SA634503	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-520-BB, CB, MB; IO-550-A, B, C, D, E, F, G, L; TSIO-520-BB, BE, CE, DB, EB, JB, KB, LB, NB, UB, VB, WB; TSIOL-550-A
SA634505	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, G; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AE, AF,
SA634511	77	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, D10, D15, E, F, J, K, L, M, MB; IO-550-D, E, F, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AE, AF, B,
SA634703	1	Continental Engines: IO-470; TSIO-470
SA635134	76	Continental Engines: TSIO-470-B1, B2, B3, C, D; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; TSIO-520-AF, C, G, H, M, P, R, T; O-470-A, B, E, G, J, K, L, M, P, R,
SA635439	1	Continental Engines: IO-520-B, C; TSIO-520-B, D, E
SA635557	1	Continental Engines: O-470-K, L, R, B, M, P
SA635623	54	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, C, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, U, UB, VB, WB; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8; O-470-A, B, E,
SA635720	5	Continental Engines: GTSIO-520-C, D; TSIO-520-A, B, C, D, E; TSIO-470-B, C, D
SA635959	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA636242	31	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8; IO-346; O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; TSIO-470-B, C, D; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-C, G, H,



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA636465	90	Continental Engines: TSIO-360-MB; TSIO-520-B, BB, BE, E, EB, T, UB, VB
SA636931	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA637083	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8
SA637268	138	Continental Engines: A-65; C-75; C-85; C-90; E-165-2; E-185-1, 3, 8, 9, 11; E-225-4-8; C-125-2; C-145-2, 2H; O-200-A, B; O-300-A, B, C, D; GO-300-A, C, D, E
SA637269	14	Continental Engines: C75; C85; C90; O-200; E-165; E-185; E-225; C-125; C-145; O-300-A, B, C, D; GO-300-A, C, D, E
SA637277-2	137	Continental Engines: GTSIO-520-F, K
SA637579	54	Continental Engines: IO-360-A, C, D, G, H, J, K, AB, CB, DB, GB, HB, JB, KB; TSIO-360-A, B, C, D, E, F, G, H, AB, CB, DB, EB, FB, GB, HB, JB, KB; LTSIO-360-E, EB, KB; IO-520-A, BA, C, D, E, F, J, K, L, M, BB, CB, MB; TSIO-520-B, C, D, E, G, H, J, K, L, M
SA637836	14	Continental Engines: GTSIO-520-C, D, F, G, H
SA637837	14	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J,
SA638172	78	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, C, D, G, H, J, K; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-360-E, EB, KB; LTSIO-520-A
SA639193	54	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, B
SA639198	51	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA639204	14	Continental Engines: O-470-B
SA639207	76	Continental Engines: TSIO-360-C, D, LB, MB
SA639282	47	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB; LTSIO-360-E, EB, KB
SA639292	54	Continental Engines: C125-2; C145-2, 2H; C75; C85; C90; GO-300-A, C, D, E; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; LTSIO-360-E, EB, KB; O-200-A, B; O-300-A, B, C, D; O-470-A, B, E, G,
SA639565	14	Continental Engines: IO-470-D, E, F, H, L, M, N, S, U, V; TSIO-470-B, C, D
SA639569	16 & 14	Continental Engines: O-470-G; IO-470-C, G, P, R, T; LIO-470-A
SA639570	51	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, G, GB, H, JB, KB, LB, MB
SA639573	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-5
SA639577	14	Continental Engines: IO-520-A, B, C, D, E, F, J, K, L; TSIO-520-B, C, D, E, G, H, J, K; GTSIO-520-C, D, F, G, H
SA639579	51	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA639580	51	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA639629	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, G; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA639640	31	Continental Engines: C125-2; C145-2, 2H; C75, 85, 90; A65, 75; GO-300; IO-360-A, C, D, G, H, J, K; LTSIO-360-E; O-200-A, B; O-300-A, B, C, D; TSIO-360-A, B, C, D, E, F, H
SA639650	49	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA639660-10KS	78	Continental Engines: GTSIO-520-D, F, H, K, L, M, N; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, B, H, HB, JB, KB, LB, MB; TSIO-520-BE; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB
SA639660-13KS	78	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, K, L, M, MB; TSIO-520-B, BB, C, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, N, NB, UB, VB, WB
SA639660-14KS	78	Continental Engines: LTSIO-360-E, KB; TSIO-360-C, D, E, F, GB, KB, LB; TSIO-520-BE
SA639660-1KS	78	Continental Engines: GTSIO-520-C
SA639660-2KS	78	Continental Engines: GTSIO-520-C
SA639660-3KS	78	Continental Engines: GTSIO-520-C
SA639660-4KS	78	Continental Engines: GTSIO-520-F, K
SA639758	54	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, K; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA640518	52	Continental Engines: O-470-K, L, R, S
SA640612	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-550-G; LTSIO-360-E, EB, KB; LTSIO-520-AE; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H,



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA641066	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB
SA641250	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AE, AF, B, B
SA641361	77	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, C, D, G, H, J, K; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-D, F, L, M, MB; IO-550-A, B, C, D, F, G, L; LTSIO-360-E, KB; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R
SA641368	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSI
SA641533	78	Continental Engines: C125-2; C145-2, 2H; IO-360-H; LTSIO-360-E, EB, KB; O-300-A, B, C, D; TSIO-360-E, EB, F, FB, GB, KB, MB3
SA641538	76	Continental Engines: C125-2; C145-2, 2H; IO-360-A, C, D, G, H, J, K; LTSIO-360-E, EB, KB; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB; IO-360-AB, CB, DB, GB, HB, JB, KB
SA641607	90	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA641651	76	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, G; LTSIO-360-E, EB, KB; L
SA641792	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F; O-200-A, B; C125-2
SA641793	97	Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SA641870	76	Continental Engines: C125-2; C145-2, 2H; O-300-A, B, C, D; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA641909	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, VB, WB; TSIOL-550-A



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA641931	54	Continental Engines: O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, BA, C, D, E, F, J, K, L, M; TSIO-520-B, C, D, E, G, H, J, K, L, M, N, P, R, T, U, VB, WB; GTSIO-520-C, D, F, H, K, L, M, N
SA641951	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; LTSIO-520-AE; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB
SA641973	54	Continental Engines: GTSIO-520 series
SA641992	71	Continental Engines: IO-360-AB, CB, DB, GB, HB, JB, KB; LTSIO-360-EB, KB; TSIO-360-AB, CB, DB, EB, FB, GB, HB, JB, KB, LB, MB
SA642238	76	Continental Engines: IO-520-BB, CB, MB; IO-550-A, B, G; TSIO-520-BB, BE, DB, EB, JB, KB, LB, NB, UB, VB, WB; TSIOL-550-A
SA642245	90	Continental Engines: C125-2; C145-2, 2H; IO-360-A, AB, C; LTSIO-360-E, EB, KB; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, JB, KB, LB, MB
SA642249	77	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; O-470-G; TSIO-520-AE, AF, C, CE, G, H, M, P, R, T
SA642250	77	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, D, E, F, J, K, L; IO-550-D, E, F, L; LTSIO-520-AE; O-470-G, P; TSIO-520-AE, AF, C, CE, G, H, M, P, R, T
SA642318	101	Continental Engines: TSIO-520-AE, AF, BB, C, CB, CE, G, H, M, MB, P, R, T, UB; IO-550-A, B, C, D, E, F, L; TSIOL-550-A
SA642335	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO
SA642337	78	Continental Engines: IO-360-AB, CB, DB, GB, HB, JB, KB; LTSIO-360-EB, KB; TSIO-360-AB, CB, DB, EB, FB, GB, HB, JB, KB, LB, MB
SA642338	71	Continental Engines: IO-520-BB, CB, MB; IO-550-A, B, G; TSIO-520-BB, BE, DB, EB, JB, KB, LB, NB, UB, VB, WB; TSIOL-550-A



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA642398	54	Continental Engines: IO-520-BB, CB, MB; IO-550-A, B, C, D, E, F, G, L; TSIO-520-BB, BE, CE, DB, EB, JB, KB, LB, NB, UB, VB, WB; TSIOL-550-A
SA642714	54	Continental Engines: C75, 85, 90; IO-470-C, E, F, G, H, J, K, N, R, S; IO-520-A, B, BA, BB, D, F, J, K, L; IO-550-D, F, G, L; O-200-A, B; O-470-A, G, J, K, L, P, R, S, U; TSIO-520-AF, C, CE, D, DB, G, H, M, P, R, T, U, UB
SA642720	54	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, R, S, U, V; IO-520-A, BB, CB, D, E, F, J, K, L, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AE, AF, BB, BE, C, CE, DB, EB, G, H, JB, KB, LB, M, NB, P,
SA642839	54	Continental Engines: IO-520-B, BA, C, M; TSIO-520-B, D, E, J, K, L, N
SA642872	76	Continental Engines: TSIO-520-T
SA642892	78	Continental Engines: IO-550-A, B, C; LTSIO-360-E, KB; TSIO-360-E, EB, F, FB, GB, KB, LB, MB; TSIOL-550-A
SA642917-1	90	Continental Engines: IO-346-A; O-470-A, B, E, G, P, K, L, M, R, S, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, C, D, E, F, J, K, L, BA, BB, CB; TSIO-520-B, C, D, E, G, H, J, K, L, N, WB, UB, AF; TSIO-470-B, C, D; IO-550-B, C
SA642917-2	90	Continental Engines: TSIO-360-MB; TSIO-520-BE
SA642917-3	90	Continental Engines: TSIO-520-BE
SA643067	97	Continental Engines: O-200-A, B
SA643233	42	Continental Engines: C75; C85; C90; O-200-A, B
SA643626	71	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; O-470-U; IO-550-A, B, C, D, E, F, G, L; TSIO-520 AE, BE, CE; TSIOL-550-A



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA643629	95	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-550-A, B, C, D, E, F, G, L; C 470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-470-B, C, D; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P
SA643766	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO
SA643767	90	Continental Engines: E165-2; E185-1, 3, 8, 9, 11; E225-4, 8; O-470-A, B, E, G, J, K, L, M, P, R, S, U; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; TSIO-470-B, C, D; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; TSIO-520-C, G, H, M, P, R
SA643873	46	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; LTSIO-520-AE; TSIO-470-B1, B2, B3, C, D; TSIO-520-AE, AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB
SA643967	54	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, A10, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, D4, E, F, G, L; O-470-B, G, K, L, M, P, R, S, U; TSIO-360-MB; TSIO-520-AF
SA646234	90	Continental Engines: IO-470-J, K; LTSIO-520-AE; TSIO-520-AE; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8; IO-346-A; O-470-A, E, J
SA646234-S		Continental Engines: IO-470-J, K; LTSIO-520-AE; TSIO-520-AE; E165-2; E185-1, 3, 8, 9, 11; E225-4, 8; IO-346-A; O-470-A, E, J
SA646254	76	Continental Engines: LTSIO-360-E, KB; TSIO-360-A, B, C, D, E, F, GB, H, JB, KB, LB, MB
SA646277	77	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; O-470-A, B, E, G, J, K, L, M, P, R, S, U, U11, U12; TSIO-520
SA646288	63	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, G, H, J, K, L, M, N, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, D, E, F, G, L; LTSIO-360-E, EB, KB; O-470-A, B, E, G, J,
SA646303	55	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; TSIO-520-B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, U, UB, VB, WB
SA646459	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA646460	78	Continental Engines: IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, JB, KB, LB, MB
SA646605	77	Continental Engines: C75; C85; C90; GTSIO-520-C, D, F, H, K, L, M, N; IO-360-A, AB, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; IO-470-C, D, E, F, F19, F23, F3, F4, F5, F7, G, H, J, K, K14, L, M, N, P, R, S, S8, U, V; IO-520-A, B, BA, BB, C, CB, D, D32, D3
SA646743	78	Continental Engines: LTSIO-360-E, EB, KB; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, GB, H, HB, JB, KB, LB, MB; LTSIO-360-E, KB
SA646846	137	Continental Engines: A-65; C-75; C-85; C-90; E-225; C-125; C-145; O-200-A, B, C, D; O-300-A, B, C, D; GO-300-A, C, D, E
SA646985	77	Continental Engines: IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-550-A, B, C, D, E, F, L; O-470-A, B, E, G, J, K, L, M, P, S, V; TSIOL-550-A; IO-520-A, BA, C, D, E, F, J, K, L, M; TSIO-520-AE, AF, B, BB, C, CE, D, DB, E, EB, G, H, J, JB, K,
SA648013	95	Continental Engines: IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB
SA648029	138	Continental Engines: O-470-U; IO-470-D, E, F, H, L, M, N, S, U, V
SA648044	147	Continental Engines: TSIO-520-AF, B, BB, BE, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P, R, T, UB, VB, WB
SA649205	95	Continental Engines: IO-520-BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; TSIOL-550-A
SA649506	86	Continental Engines: C125-2; C145-2, 2H; IO-360-A, AB, B, C, CB, D, DB, G, GB, H, HB, J, JB, K, KB; O-300-A, B, C, D; TSIO-360-A, AB, B, C, CB, D, DB, E, EB, F, FB, G, GB, H, HB, J, JB, K, KB, LB, MB; LTSIO-360-E, KB
SA649520		Continental Engines: IO-520-B, BA, BB, C, CB, M, MB; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; IO-550-B, C
SA649520-A3	137	Continental Engines: IO-520-B, BA, BB, C, CB, M, MB; TSIO-520-B, BB, BE, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, UB, VB, WB; IO-550-B, C



FAA-PMA Parts Eligibility for Continental Engines

Part #	Supplement	Eligibility
SA65000S0	148	Continental Engines: A-65-1, A-65-3, A65-6, A65-7, A65-8, A65-9, A65-12, A65-14
SA652541	147	Continental Engines: GTSIO-520-C, D, F, H, K, L, M, N; IO-470-C, D, E, F, G, H, J, K, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; IO-550-A, B, C, G; LTSIO-520-AE; O-470-A, B, E, G, J, K, L, M, P, R, S, U; TSIO-520-AE, AF,
SA652947	110	Continental Engines: IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B, C, D; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M, N, NB, P,
SA652984	99	Continental Engines: IO-470-C, D, E, F, G, H, L, M, N, P, R, S, U, V; IO-520-A, B, BA, BB, C, CB, D, E, F, J, K, L, M, MB; O-470-B, G, K, L, M, P, R, S, U; TSIO-470-B1, B2, B3, C, D; TSIO-520-AF, B, BB, C, CE, D, DB, E, EB, G, H, J, JB, K, KB, L, LB, M,
SA653359	153	Continental Engines: IO-346; IO-520-B, BA, BB, C, CB, M, MB; IO-550-A, B, C, G; TSIO-520-B, BB, D, DB, E, EB, J, JB, K, KB, L, LB, N, NB, U, UB, V, VB, W, WB; TSIOL-550-A, B; TSIO-550-B
SAC10203		Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-8, 12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F
SAF10202		Continental Engines: C75-8, 12, 14, 16, 8F, 12F, 14F, 16F; C85-12, 14, 16, 8F, 12F, 14F, 16F; C90-8, 12, 14, 16, 8F, 12F, 14F, 16F; O-200-A, B; C125-2; C145-2, 2H; O-300-A, B, C, D; GO-300-A, C, D, E, F